


TECHNICL NOTES

NOTES	CONTENT
GENERAL NOTES	
Metal structure treatment	Iron structures should be painted to prevent rust and improve equipment life. - Remove loose rust with a wire brush, sandpaper or chemical rust remover. - If applicable, sand areas where paint is chipping until surface is smooth. - Remove dust or oil with a degreaser or denatured alcohol. - Prime surface to protect against rust and corrosion
Parts to buy	- Clamp bolt 12.5 Screw Ring M12 GOST 4751-73 Standard CSN 02 1369 M12 - Hex nut 12.5 AS 1112 - M12 Type 5 Standard AS 1112 METRIC M12 - Hex head bolt 12.5 ANSI B18.2.3.5M - M12 x 1,75 x 55 Standard Hex Bolt - Washers AS 1237 - 12 mm Standard Flat metal washers for general engineering purposes (metric series)
	-
...	...
...	...

PROJECT	CREATED BY	APPROVED BY	DATE	VERSION
Ox-drawn Plough	L. Ruda	A. Morillo	09/09/2021	1.0
PART NAME	FILE NAME			POS
Technical notes	pac_odp_ox-drawn_plough			C1
DEVELOPED BY	REDESIGNED BY	DOC. TYPE	MATERIAL	QUANTITY
		Technical notes		
Practical Action	OHO e.V.	LICENCE	SCALE	SHEET
		CC-BY-SA 4.0		5 /26