


TECHNICAL NOTES

NOTES	CONTENT
GENERAL NOTES	
Metal structure treatment	Iron structures should be painted to prevent rust and improve equipment life. - Remove loose rust with a wire brush, sandpaper or chemical rust remover. - If applicable, sand areas where paint is chipping until surface is smooth. - Remove dust or oil with a degreaser or denatured alcohol. - Prime surface to protect against rust and corrosion

PROJECT Hammer Mill for corn processing	CREATED BY E. Araujo	APPROVED BY A. Morillo	DATE 09/08/2021	VERSION 1.0
PART NAME Technical notes	FILE NAME oho_hm_hammer-mill-for-corn-processing.dwg			POS C1
DEVELOPED BY Apt Abatec	REDESIGNED BY  OHO e.V.	DOC. TYPE Technical notes	MATERIAL	QUANTITY
		LICENCE CC-BY-SA 4.0	SCALE	SHEET 7/42